

Firmware Release Notes

Product: Multi-CH Encoder System Firmware

Version: A8D-R2N-V2.06.00-AC

Date: 3, Sep, 2009

To upgrade firmware to multi-channel system encoder, please make sure you follow below sequence to upgrade firmware. Otherwise, you might fail to find channel after upgrade.

For Channels with Encoder firmware V2.xx.xx (SED series), Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-M2N-V2.09.11 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.05.02 or above

For Channels with Encoder firmware V3.xx.xx (ACD series), Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-220-V3.09.14 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.05.02 or above
3. Upgrade camera profile via IP utility or camera profile loader

Important Notice

Please be sure to power off the device and power on again after upgrading firmware, to complete the firmware upgrade process properly.

Limitation

1. None

New Feature

1. None

Enhancement

1. Bug fixed

Modified

1. None

Remove

1. None