

# Firmware Release Notes

**Product:** Multi-CH Encoder System Firmware

**Version:** A8D-R2N-V2.06.00-AC

**Date:** 23, Nov, 2009

To upgrade firmware to multi-channel system encoder, please make sure you follow below sequence to upgrade firmware. Otherwise, you might fail to find channel after upgrade.

For Channels with Encoder firmware V2.xx.xx (SED series), Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-M2N-V2.09.11 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.05.02 or above

For Channels with Encoder firmware V3.xx.xx (ACD series), Please follow the sequence below:

1. Upgrade encoder channel firmware
2. Upgrade encoder system firmware
3. If you need to upgrade device profile, please do so after upgrading channel and system firmwares, via IP utility or profile loader

**If you upgrade from 3.08.08 or earlier, do not upgrade directly to 3.11.13. Please upgrade to 3.09.14 first, then upgrade to 3.11.13.**

Firmware Before Upgrading	Upgrade Path
Channel : 3.08.08 or earlier System: 2.05.02 or earlier	Upgrade channel to 3.09.14 → → Upgrade Channel to 3.11.13. → Upgrade system to 2.06.00. <b>Warning: Do not upgrade channel firmware directly to 3.11.13 Device will show error message "Firmware Version Mismatch", and upgrade will not complete.</b>
Channel : 3.09.14 or later System: 2.05.02 or earlier	Upgrade Channel to 3.11.13. → Upgrade system to 2.06.00.

Channel : 3.09.14 or later System: 2.06.00	Upgrade Channel to 3.11.13.
--	-----------------------------

### **Important Notice**

**Please be sure to power off the device and power on again after upgrading firmware, to complete the firmware upgrade process properly.**

#### **Limitation**

1. None

#### **New Feature**

1. Event Handler (3.11.13)

#### **Enhancement**

1. Bug fixed

#### **Modified**

1. None

#### **Remove**

1. None