

# Firmware Release Notes

**Product:** Multi-CH Encoder System Firmware

**Version:** A8D-R2N-V2.05.02-AC

**Date:** 2 Mar, 2009

To upgrade firmware to multi-channel system encoder, please make sure you follow below sequence to upgrade firmware. Otherwise, you might fail to find channel after upgrade.

For Main Stream Product Encoder, Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-M2N-V2.09.11 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.05.02 or above

For Entry Product Encoder, Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-220-V3.09.14 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.05.02 or above
3. Upgrade camera profile via IP utility or camera profile loader

## **Limitation**

1. None

## **New Feature**

1. Add URL for DHCP with Hostname control, DHCP\_BY\_HOSTNAME

## **Enhancement**

1. Bug fixed

## **Modified**

1. None

## **Remove**

1. None