

Firmware Release Notes

Product: Multi-CH Encoder System Firmware

Version: A8D-R2N-V2.04.01-AC

Date: 22th July, 2008

To upgrade firmware to multi-channel system encoder, please make sure you follow below sequence to upgrade firmware. Otherwise, you might fail to find channel after upgrade.

For Main Stream Product Encoder, Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-M2N-V2.08.11 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.04.01 or above

For Entry Product Encoder, Please follow the sequence below:

1. Upgrade encoder channel firmware to A1D-220-V3.08.08 or above
2. Upgrade encoder system firmware to A8D-R2N-V2.04.01 or above
3. Upgrade camera profile via IP utility or camera profile loader

Limitation

1. None

New Feature

1. None

Enhancement

1. None

Modified

1. Change the multicast IP address region to 224.5.0.1 ~ 239.255.255.255

Remove

1. None